


## HEX SOCKET CAP SCREWS



### M8, 5 A/F

#### Screw

M8 x 16  
 M8 x 20  
 M8 x 25  
 M8 x 30  
 M8 x 35  
 M8 x 40  
 M8 x 45  
 M8 x 50  
 M8 x 60  
 M8 x 70  
 M8 x 80  
 M8 x 90

#### Part no.


(steel, zincplated)

21.1200/0  
 21.1202/0  
 21.1204/0  
 21.1206/0  
 21.1208/0  
 21.1210/0  
 21.1211/0  
 21.1212/0  
 21.1214/0  
 21.1282/0  
 21.1225/0  
 21.1226/0

#### Part no.

(stainless steel)

21.1200/1  
 21.1202/2  
 21.1204/1  
 -----  
 21.1208/1  
 -----  
 21.1212/1  
 -----  
 -----  
 -----  
 -----



### M6, 4 A/F

#### Screw

M6 x 12  
 M6 x 16  
 M6 x 20  
 M6 x 25  
 M6 x 30  
 M6 x 35  
 M6 x 40  
 M6 x 45  
 M6 x 50  
 M6 x 60  
 M6 x 80

#### Part no.

(steel, zincplated)

21.1143/0  
 21.1238/0  
 21.1240/0  
 21.1242/0  
 21.1243/0  
 21.1245/0  
 21.1247/0  
 21.1172/0  
 21.1171/0  
 21.1154/0  
 21.1199/0

#### Part no.

(stainless steel)

-----  
 21.1238/1  
 21.1340/1  
 21.1242/1  
 21.1243/1  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 21.1199/1

### M5, 4 A/F

#### Screw

M5 x 12  
 M5 x 16  
 M5 x 20  
 M5 x 25  
 M5 x 30  
 M5 x 40  
 M5 x 45

#### Part no.

(steel, zincplated)

21.1220/0  
 21.1235/0  
 21.1222/0  
 21.1224/0  
 21.1237/0  
 21.1284/0  
 21.1219/0

#### Part no.

(stainless steel)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----