



DON'T TIGHTEN POWER-LOCK
BUTTON HEAD SCREW ALL THE
WAY DOWN. LEAVE ABOUT A 1mm
GAP SO THE POWER-LOCK HAS
A LITTLE PLAY